

APPENDIX C
TV Inspection Logs

Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 08:36	Dry - No precipitation	durina	J.HASHEM	000-0000-0000	2419-367	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	CHESTNUT S	ST		Sanitary Sewage Pipe		
Upstream MH No:	Do	ownstream	MH No:	Direction:	Total length:	Length surveyed:
2419	30	67		D	104.900 ft.	104.880 ft.
Purpose: Pipe joi	int length: He	eight:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8	in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	0				0	0							
3	0	3	16	4331	3.2	0	0	0	0000	0.0	16	3.2	4.3	
4	0	12				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 08:51	Dry - No precipitation	on during	J.HASHEM	000-0000-0000	367-366	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	CHESTNU	T ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	· Total length:	Length surveyed:
367		366		D	262.202 ft.	262.201 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	4				0	0							
2	0	4				0	0							
3	0	15	28	5135	2.3	0	0	0	0000	0.0	28	2.3	5.1	
4	0	0				0	0							
5	0	5				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 11:33	Dry - No	ion during	alberto	u-0220-70308624	1526-1958	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	COTTAGE	ST		Sanitary Sewage Pipe		<b>」</b>
Upstream MH No:		Downstrea	am MH No:	Direction:	• Total length:	Length surveyed:
1526		1958		U	157.322 ft.	157.320 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe		ACCIDENTALY TY	PED IN WRONG MH #


			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	0				0	0							
3	0	0	6	4112	2.0	0	0	0	0000	0.0	6	2.0	4.1	
4	0	4				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 10:08	Dry - No	ion during	alberto	u-0220-70308624	1526-1527	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	COTTAGE	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	nm MH No:	Direction:	Total length:	Length surveyed:
1526		1527		D	192.550 ft.	192.547 ft.
Purpose: Pipe	joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			


			Structura	al:				O&M:				Overall:		
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	4							
2	0	0				0	0							
3	0	9	13	4133	3.2	0	3	7	3114	1.4	20	2.2	4.1	
4	0	4				0	0							
5	0	0				0	0							



Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 12:03	Dry - No precipitation du	J.HASHEM	000-0000-0000	1494/151	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	EAST MAIN ST		Sanitary Sewage Pipe		
Upstream MH No:	Dow	nstream MH No:	Direction:	Total length:	Length surveyed:
1494	151		D	205.700 ft.	205.658 ft.
Purpose: Pipe jo	int length: Heig	ht: Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	15 ir	n. Vitrified Clay			


			Structura	ıl:				O&M:				Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk	
1	0	0				0	0								
2	0	24				0	0								
3	0	18	42	362A	2.3	0	0	0	0000	0.0	42	2.3	3.6		
4	0	0				0	0								
5	0	0				0	0								






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 14:11	Dry - No precipitation	n during	J.HASHEM	000-0000-0000	151/887	
	survey	on during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	EAST MAIN	I ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
151		887		D	207.000 ft.	206.958 ft.
Purpose: Pipe jo	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		15 in.	Vitrified Clay Pipe			


			Structura	al:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	30				0	0							
3	0	69	100	3C2B	2.6	0	0	0	0000	0.0	100	2.6	4.0	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 14:30	Dry - No precipitation	n during	J.HASHEM	000-0000-0000	887/1750	
	survey	on during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	EAST MAIN	I ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	ım MH No:	Direction:	· Total length:	Length surveyed:
887		1750		D	253.800 ft.	253.794 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		15 in.	Vitrified Clay Pipe			


			Structura	ıl:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	3				0	0							
2	0	10				0	0							
3	0	9	30	4233	2.3	0	0	0	0000	0.0	30	2.3	4.2	
4	0	8				0	0							
5	0	0				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 14:50	Dry - No precipitation du	J.HASHEM	000-0000-0000	1750/1749	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	EAST MAIN ST		Sanitary Sewage Pipe		
Upstream MH No:	Dowr	nstream MH No:	Direction:	Total length:	Length surveyed:
1750	1749		D	267.406 ft.	267.405 ft.
Purpose: Pipe joi	int length: Heigh	nt: Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	15 in	. Vitrified Clay Pipe			


			Structura	al:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	4				0	1							
2	0	10				0	0							
3	0	9	28	5133	2.2	0	0	1	1100	1.0	29	2.1	5.1	
4	0	0				0	0							
5	0	5				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 12:54	Dry - No precipitation during	J.HASHEM	000-0000-0000	1749/894	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	EAST MAIN ST		Sanitary Sewage Pipe		
Upstream MH No:	Downstre	eam MH No:	Direction:	Total length:	Length surveyed:
1749	894		D	167.330 ft.	167.328 ft.
Purpose: Pipe joi	nt length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	15 in.	Vitrified Clay Pipe			

			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	4							
2	0	6				0	0							
3	0	6	12	3223	2.4	0	3	115	4D31	3.6	127	3.4	5.0	
4	0	0				0	108							
5	0	0				0	0							




Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 13:33		tion during	J.HASHEM	000-0000-0000	894/893	
	survey	tion during				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MAIN ST			Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
894		893		D	181.340 ft.	181.339 ft.
Purpose: Pipe	joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		15 in.	Vitrified Clay Pipe			

			Structura	nl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	0				0	0							
3	0	0	2	1200	1.0	0	0	132	4E00	4.0	134	3.8	5.0	
4	0	0				0	132							
5	0	0				0	0							




Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200820 07:54	Dry - No precipitation during	K.Lang	UO-200-70308438	893-892	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
Vernon	Main ST		Sanitary Sewage Pipe		
Upstream MH No:	Downstr	eam MH No:	Direction:	Total length:	Length surveyed:
893	891		D	130.701 ft.	130.700 ft.
Purpose: Pipe jo	int length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	15 in.	Vitrified Clay Pipe		manhole correction	on

			Structura	ıl:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	0				0	0							
3	0	0	0	0000	0.0	0	0	65	4B11	3.8	65	3.8	5.0	
4	0	0				0	64							
5	0	0				0	0							




Start date/tim	e: Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200820 0	8:13 Dry - No	tion during	K.Lang	UO-200-70308438	892-891	
	survey	lion during				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
Vernon	Main ST			Sanitary Sewage Pipe		
Upstream MH	No:	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
892		891		D	177.340 ft.	177.336 ft.
Purpose:	Pipe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		15 in.	Vitrified Clay Pipe		manhole correcti	on 892-891


	Structural:					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	3				0	2							
2	0	14				0	0							
3	0	3	20	3127	1.8	0	0	6	4112	2.0	26	1.9	4.1	
4	0	0				0	4							
5	0	0				0	0							





Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:				
20200820 08:43	Dry - No precipitation	n during	K.Lang	UO-200-70308438	891-2655				
	survey	ii duriiig							
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:				
			Light Cleaning		TIG001-23				
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:			
Vernon	Main ST			Sanitary Sewage Pipe					
Upstream MH No:	1	Downstrear	n MH No:	Direction:	Total length:	Length surveyed:			
891		2655		D	275.315 ft.	275.311 ft.			
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:				
Maintenan ce Related ———		15 in.	Vitrified Clay Pipe						

	Structural:							O&M:			Overall:				
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk	
1	0	3				0	25								
2	0	34				0	4								
3	0	3	40	312B	1.9	0	0	29	221D	1.1	69	1.4	3.1		
4	0	0				0	0								
5	0	0				0	0								











Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200820 09:4		ion during	K.Lang	UO-200-70308438	2654-2653	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
Vernon	Main ST			Sanitary Sewage Pipe		
Upstream MH No	0:	Downstrea	m MH No:	Direction:	· Total length:	Length surveyed:
2654		2653		D	271.410 ft.	271.408 ft.
Purpose: Pi	pe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		15 in.	Vitrified Clay Pipe			

	Structural:							O&M:			Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	8				0	0							
2	0	4				0	0							
3	0	12	24	3422	1.7	0	0	0	0000	0.0	24	1.7	3.4	
4	0	0				0	0							
5	0	0				0	0							




Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:				
20200820 10:11	Dry - No precipitation	n during	K.Lang	UO-200-70308438	2653-1756				
	survey								
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:				
			Light Cleaning		TIG001-23				
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:			
Vernon	Main ST			Sanitary Sewage Pipe					
Upstream MH No:	[	Downstream MH No:		Direction:	Total length:	Length surveyed:			
2653		1756		D	276.113 ft.	276.111 ft.			
Purpose: Pipe joi	int length:	Height:	Material:	LateralsCounter:	Additional info:				
Maintenan ce Related		15 in.	Vitrified Clay Pipe						


	Structural:							O&M:			Overall:				
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk	
1	0	6				0	3								
2	0	4				0	0								
3	0	3	13	3122	1.4	0	0	3	1300	1.0	16	1.3	3.1		
4	0	0				0	0								
5	0	0				0	0								



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 12:45	Dry - No	ion during	alberto	u-0220-70308624	601-1955	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:	reet: Location code:		Pipe use:	Drainage area:	Flow control:
VERNON CT	ELM ST			Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
601		1955		D	303.935 ft.	303.933 ft.
Purpose: Pipe	joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay Pipe		CANT SEE MH DU	E TO L SHAPED INVERT


	Structural:							O&M:			Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	3				0	3							
2	0	2				0	0							
3	0	6	31	4532	2.8	0	0	3	1300	1.0	34	2.4	4.5	
4	0	20				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 13:		ion during	alberto	u-0220-70308624	1955-1954	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	ELM ST			Sanitary Sewage Pipe		
Upstream MH N	0:	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
1955		1954		D	249.100 ft.	249.091 ft.
Purpose: Pi	pe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			

			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	0				0	0							
3	0	6	23	5143	3.8	0	0	1	1100	1.0	24	3.4	5.1	
4	0	12				0	0							
5	0	5				0	0							




Surveyed by: Weather: Start date/time: Certificate number: Pipe segment ref.: 20200817 07:57 Dry - No UO-200-70308438 MH1955-MH1954 K.Lang precipitation during survey Owner: Customer: Pre-cleaning: Date cleaned: Project name: **Light Cleaning** TIG001-23 Flow control: City: Street: Location code: Pipe use: Drainage area: **ELM STREET Sanitary Sewage VERNON CT** Pipe Upstream MH No: Downstream MH No: Direction: Total length: Length surveyed: MH1955 MH1954 305.335 ft. D 305.334 ft. Purpose: Pipe joint length: Height: Material: LateralsCounter: Additional info: Maintenan 8 in. Vitrified Clay ce Related Pipe


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	3				0	0							
2	0	2				0	2							
3	0	0	13	4221	2.2	0	6	8	3221	2.7	21	2.3	4.2	
4	0	8				0	0							
5	0	0				0	0							



Start date/time:	: Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200817 09:		tion during	K.Lang	UO-200-70308438	MH1954-MH1953	
	survey					
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	ELM ST			Sanitary Sewage Pipe		
Upstream MH N	lo:	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
MH1954		MH1953		D	202.300 ft.	202.255 ft.
Purpose: Pi	ipe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			

			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	3				0	0							
2	0	0				0	0							
3	0	3	10	4131	2.0	0	6	6	3200	3.0	16	2.3	4.1	
4	0	4				0	0							
5	0	0				0	0							







National Water Main Cleaning


Co.


25 Marshall Street Canton, MA 02021 Office: 800-422-0815 Fax: 781-828-2473


# **NWMCC INSPECTION REPORT**

Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 08:11	Dry - No precipitation during	J.HASHEM	000-0000-0000	1524/610	
	survey	<u>'</u>			
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	LAWRENCE ST		Sanitary Sewage Pipe		
Upstream MH No:	Downstr	eam MH No:	Direction:	Total length:	Length surveyed:
1524	610		D	247.190 ft. 247.189 ft.	
Purpose: Pipe joi	int length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8 in.	Vitrified Clay Pipe			

			Structura	ıl:				O&M:				Ove	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	7				0	2							
2	0	4				0	0							
3	0	3	14	3122	1.4	0	0	2	1200	1.0	16	1.3	3.1	
4	0	0				0	0							
5	0	0				0	0							








Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 08:38	Dry - No	tion during	J.HASHEM	000-0000-0000	610/611	
	survey	g				
Owner:	Customer		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning	<u> </u>	TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	LAWREN	CE ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
610	611			D	226.075 ft. 226.073 ft.	
Purpose: Pipe joi	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay			


			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	5				0	9							
2	0	6				0	4							
3	0	3	19	5131	1.9	0	0	13	2219	1.2	32	1.5	5.1	
4	0	0				0	0							
5	0	5				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 09:33	Dry - No precipitation	during	J.HASHEM	000-0000-0000	611/612	
	survey	i during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Heavy Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	LAWRENCE	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
611		612		D	230.980 ft.	230.977 ft.
Purpose: Pipe jo	oint length: F	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	7				0	4							
2	0	4				0	0							
3	0	0	15	4122	1.5	0	3	7	3114	1.4	22	1.5	4.1	
4	0	4				0	0							
5	0	0				0	0							





Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 10:11	Dry - No	ion during	J.HASHEM	000-0000-0000	612/1523	
	survey	lion during				
Owner:	Customer	!	Pre-cleaning:	Date cleaned:	Project name:	
			Heavy Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	WEBSTE	R ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
612		1523		D	200.100 ft.	200.053 ft.
Purpose: Pipe	joint length:	Height:	Material:	LateralsCounter:	- Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			


			Structura	al:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	12				0	5							
2	0	12				0	2							
3	0	33	57	3A26	2.0	0	0	7	2115	1.2	64	1.8	4.0	
4	0	0				0	0							
5	0	0				0	0							




Mainline length: 200.100 ft.

Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 10:35	Dry - No precipitation	on during	J.HASHEM	000-0000-0000	1523/1521	
	survey	on during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning	<u> </u>	TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	WEBSTER	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
1523		1521		D	259.900 ft.	259.899 ft.
Purpose: Pipe joi	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay			


			Structura	nl:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	20				0	3							
2	0	10				0	2							
3	0	105	135	3F25	2.2	0	0	5	2113	1.2	140	2.2	4.0	
4	0	0				0	0							
5	0	0				0	0							






Mainline length; 259,900 ft.






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 12:02	Dry - No	tion during	J.HASHEM	000-0000-0000	1522/1521	
	survey	tion during				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MOUNTA	IN ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
1522		1521		D	370.200 ft.	370.184 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			

			Structura	al:				O&M:			Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	10				0	8							
2	0	0				0	4							
3	0	3	13	311A	1.2	0	0	12	2218	1.2	25	1.2	3.1	
4	0	0				0	0							
5	0	0				0	0							





Omitted: 55.36 ft.



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 12:32	Dry - No precipitation	n during	J.HASHEM	000-0000-0000	1521/609	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MOUNTAIN	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrear	m MH No:	Direction:	Total length:	Length surveyed:
1521		609		D	170.633 ft.	170.631 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


			Structura	ıl:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	3							
2	0	6				0	0							
3	0	6	13	3223	2.2	0	0	3	1300	1.0	16	1.8	3.2	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 12:48	Dry - No precipitation during	J.HASHEM	000-0000-0000	609/608	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MOUNTAIN ST		Sanitary Sewage Pipe		
Upstream MH No:	Downstre	eam MH No:	Direction:	Total length:	Length surveyed:
609	608		D	111.500 ft.	111.485 ft.
Purpose: Pipe joi	nt length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8 in.	Vitrified Clay Pipe			


			Structura	ıl:		O&M:					Overall:				
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk	
1	0	3				0	0								
2	0	0				0	0								
3	0	0	3	1300	1.0	0	0	4	4100	4.0	7	1.8	4.1		
4	0	0				0	4								
5	0	0				0	0								







Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200810 14:08	Dry - No precipitation durin	J.HASHEM	000-0000-0000	608/607	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MOUNTAIN ST		Sanitary Sewage Pipe		
Upstream MH No:	Downst	ream MH No:	Direction:	Total length:	Length surveyed:
608	607		D	318.045 ft.	318.044 ft.
Purpose: Pipe joi	nt length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8 in.	Vitrified Clay Pipe			

			Structura	ıl:				O&M:		Overall:				
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	10				0	1							
2	0	6				0	0							
3	0	12	28	3423	1.6	0	3	4	3111	2.0	32	1.7	3.5	
4	0	0				0	0							
5	0	0				0	0							









Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 07:21	Dry - No precipitation durin survey	g J.HASHEM	000-0000-0000	2157-1525	
Owner:	Customer:	Pre-cleaning: Light Cleaning	Date cleaned:	Project name: TIG001-23	
City: VERNON CT	Street: PROSPECT ST	Location code:	Pipe use: Sanitary Sewage Pipe	Drainage area:	Flow control:
Upstream MH No: 2157	Downst <b>1525</b>	ream MH No:	Direction:	Total length: 308.340 ft.	Length surveyed: 308.336 ft.
Purpose: Pipe jo  Maintenan ce Related	int length: Height: 8 in.	Material: Vitrified Clay Pipe	LateralsCounter:	Additional info:	


	Structural:					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	2				0	14							
3	0	6	43	5246	3.6	0	0	14	2700	2.0	57	3.0	5.2	
4	0	24				0	0							
5	0	10				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200819 08:39	Dry - No precipitation d	J.HASHEM uring	000-0000-0000	1525/120	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PROSPECT ST	·	Sanitary Sewage Pipe		
Upstream MH No:	Dov	vnstream MH No:	Direction:	Total length:	Length surveyed:
1525	120	)	D	161.125 ft.	161.123 ft.
Purpose: Pipe jo	int length: Hei	ght: Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8 ii	n. Vitrified Clay			


	Structural:					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	5				0	1							
2	0	0				0	0							
3	0	9	18	4133	2.0	0	0	5	4111	2.5	23	2.1	4.2	
4	0	4				0	4							
5	0	0				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 11:17	Dry - No	tion during	J.HASHEM	000-0000-0000	3057-3056	
	survey	ution during				
Owner:	Custome	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PROSPE	CT ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
3057		3056		D	148.715 ft.	148.714 ft.
Purpose: Pipe jo	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	0				0	0							
3	0	3	5	3112	1.7	0	0	0	0000	0.0	5	1.7	3.1	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 11:40	Dry - No	ion during	alberto	u-0220-70308624	3056-605	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PROSPEC	CT ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
3056		605		D	87.900 ft.	87.867 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay			


	Structural: rade Defects Segment Pipe Quick Pipe Ratin					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	2				0	0							
3	0	0	4	2112	1.3	0	0	0	0000	0.0	4	1.3	2.1	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 12:02	Dry - No precipitation du	alberto	u-0220-70308624	605-604	
	survey				
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PARK ST ST		Sanitary Sewage Pipe		
Upstream MH No:	Dow	nstream MH No:	Direction:	Total length:	Length surveyed:
605	604		D	141.010 ft.	141.008 ft.
Purpose: Pipe j	oint length: Heig	ght: Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	8 in	. Vitrified Clay Pipe			


			Structura	al:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	2				0	0							
3	0	6	8	3221	2.7	0	0	1	1100	1.0	9	2.2	3.2	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 12:15	Dry - No	tion during	alberto	u-0220-70308624	604-2160	
	survey					
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PARK ST	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
604		2160		D	141.810 ft.	141.809 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay			


			Structura	ıl:		O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	1							
2	0	2				0	0							
3	0	3	18	4331	3.0	0	0	1	1100	1.0	19	2.7	4.3	
4	0	12				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 12:31	Dry - No	tion during	alberto	u-0220-70308624	2160-1518	
	survey	ution during				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PARK ST	r st		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
2160		1518		D	205.800 ft.	205.758 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	3							
2	0	0				0	0							
3	0	15	19	4135	3.2	0	0	3	1300	1.0	22	2.4	4.1	
4	0	4				0	0							
5	0	0				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200811 13:2		ion during	alberto	u-0220-70308624	1518-2831	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PARK ST	ST		Sanitary Sewage Pipe		
Upstream MH No	):	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
1518		2831		D	178.940 ft.	178.937 ft.
Purpose: Pip	e joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	0				0	0							
3	0	0	14	4312	2.8	0	0	4	4100	4.0	18	3.0	4.4	
4	0	12				0	4							
5	0	0				0	0							






Start date/time: 20200811 13:49	Weather:	I	Surveyed by: alberto	Certificate number: u-0220-70308624	Pipe segment ref.: 2831-1517	
20200011 10.43		ion during		u-0220-7000024	2001-1017	
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	PARK ST	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
2831		1517		D	206.400 ft.	206.358 ft.
Purpose: Pipe jo	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	0				0	0							
3	0	3	16	4331	3.2	0	0	0	0000	0.0	16	3.2	4.3	
4	0	12				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 07:37	Dry - No precipitation	on during	alberto	u-0220-70308624	1212-1211	
	survey	on during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	SCHOOL S	ST .		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
1212	1			D	201.700 ft.	201.654 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	0							
2	0	0				0	0							
3	0	27	27	3900	3.0	0	0	0	0000	0.0	27	3.0	3.9	
4	0	0				0	0							
5	0	0				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 08:04	Dry - No precipitat	ion during	alberto	u-0220-70308624	1211-2832	
	survey					
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	SCHOOL	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
1211		2832		D	225.500 ft.	225.473 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay Pipe			


			Structura	al:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	4				0	0							
3	0	9	18	4133	2.6	0	0	0	0000	0.0	18	2.6	4.1	
4	0	4				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200812 08:40	Dry - No	ion during	alberto	u-0220-70308624	2832-1518	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	SCHOOL	ST		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	ım MH No:	Direction:	· Total length:	Length surveyed:
2832		1518		D	299.230 ft.	299.229 ft.
Purpose: Pipe j	oint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	3							
2	0	2				0	0							
3	0	18	33	4336	3.0	0	0	3	1300	1.0	36	2.6	4.3	
4	0	12				0	0							
5	0	0				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200818 13:08	Dry - No precipitation	during	J.HASHEM	000-0000-0000	418/2518	
	survey	i during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	LEIGON DR			Sanitary Sewage Pipe		
Upstream MH No:		Downstrear	m MH No:	Direction:	Total length:	Length surveyed:
418		2518		D	302.232 ft.	302.231 ft.
Purpose: Pipe j	oint length: F	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	2							
2	0	22				0	0							
3	0	0	26	412A	2.2	0	3	13	4231	2.6	39	2.3	4.3	
4	0	4				0	8							
5	0	0				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200818 15:02	Dry - No precipitation durin survey	g J.HASHEM	000-0000-0000	1273/1274	
Owner:	Customer:	Pre-cleaning: Light Cleaning	Date cleaned:	Project name: TIG001-23	
City: VERNON CT	Street: MARY LN	Location code:	Pipe use: Sanitary Sewage Pipe	Drainage area:	Flow control:
Upstream MH No: 1273	Downst <b>1274</b>	ream MH No:	Direction:	Total length:  262.005 ft.	Length surveyed: 262.001 ft.
Purpose: Pipe joi  Maintenan ce Related	int length: Height: 8 in.	Material: Vitrified Clay Pipe	LateralsCounter:	Additional info:	


	Structural:  Grade Defects Segment Pipe Quick Pipe Rating					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	10				0	0							
3	0	0	10	2500	2.0	0	3	4	3111	2.0	14	2.0	3.1	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200818 08:27	Dry - No	ion during	J.HASHEM	000-0000-0000	750/1627	
	survey	lion during				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	MARY LN	ı		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	I Total length:	Length surveyed:
750		1627		D	245.390 ft.	245.388 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe			


	Structural: rade Defects Segment Pipe Quick Pipe Rating							O&M:			Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	2							
2	0	10				0	0							
3	0	0	12	2512	1.7	0	3	5	3112	1.7	17	1.7	3.1	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200911 11:32	Dry - No precipitation during survey	K.Lang	UO-200-70308438	2678-2677	
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	REGAN RD		Sanitary Sewage Pipe		
Upstream MH No:	Downstr	eam MH No:	Direction:	Total length:	Length surveyed:
2678	2677		D	196.853 ft.	196.851 ft.
Purpose: Pipe jo	int length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	12 in.	Reinforced Concrete Pipe		V10 COMPUTER LA	AG PROBLEMS

	Structural:					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	0				0	72							
3	0	15	15	3500	3.0	0	0	73	2F11	2.0	88	2.1	3.5	
4	0	0				0	0							
5	0	0				0	0							




Start date/ti	me: Wea	ther:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200911		- No cipitation during	K.Lang	UO-200-70308438	2677-2676	
	sur					
Owner:	Cust	tomer:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Stre	et:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON C	T REC	SAN RD		Sanitary Sewage Pipe		
Upstream MI	H No:	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
2677		2676		U	107.600 ft.	107.582 ft.
Purpose:	Pipe joint lengt	h: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		12 in.	Reinforced Concrete Pipe		V10 REVERSE SUF	RVEY


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	0				0	40							
3	0	57	57	3B00	3.0	0	0	41	2C11	2.0	98	2.4	4.0	
4	0	0				0	0							
5	0	0				0	0							



Start date/time:	Weather:	Surveyed by:	Certificate number:	Pipe segment ref.:	
20200911 13:06	Dry - No precipitation during survey	K.Lang	UO-200-70308438	2676-926	
Owner:	Customer:	Pre-cleaning:	Date cleaned:	Project name:	
		Light Cleaning		TIG001-23	
City:	Street:	Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	CENTER RD		Sanitary Sewage Pipe		
Upstream MH No:	Downstrea	am MH No:	Direction:	Total length:	Length surveyed:
2676	926		D	203.360 ft.	203.356 ft.
Purpose: Pipe join	t length: Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related	12 in.	Asbestos Cement		V10	


	Structural:  Grade Defects Segment Pipe Quick Pipe Rating					O&M:					Overall:			
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	0							
2	0	0				0	18							
3	0	30	30	3A00	3.0	0	0	18	2900	2.0	48	2.5	4.0	
4	0	0				0	0							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200911 13:58	Dry - No precipita	tion during	K.Lang	UO-200-70308438	926-925	
	survey					
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	CENTER	RD		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	ım MH No:	Direction:	· Total length:	Length surveyed:
926		925		D	295.930 ft.	295.927 ft.
Purpose: Pipe jo	int length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related		12 in.	Asbestos Cement		V10	

			Structura	ıl:				O&M:				Ove	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	0							
2	0	0				0	90							
3	0	3	3	3100	3.0	0	0	90	2H00	2.0	93	2.0	3.1	
4	0	0				0	0							
5	0	0				0	0							




Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200911 14:18		tion during	K.Lang	UO-200-70308438	925-1262	
	survey			5		
Owner:	Customer	:	Pre-cleaning: Light Cleaning	Date cleaned:	Project name: TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	CENTER	RD		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
925		1262		D	294.630 ft.	294.626 ft.
Purpose: Pipe	joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		12 in.	Asbestos Cement		V10	


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	0							
2	0	0				0	2							
3	0	3	3	3100	3.0	0	0	2	2100	2.0	5	2.5	3.1	
4	0	0				0	0							
5	0	0				0	0							



Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200820 14:06		ion during	K.Lang	UO-200-70308438	163-1633	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON	REGAN R	D		Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	· Total length:	Length surveyed:
1632		1633		D	278.615 ft.	278.613 ft.
Purpose: Pipe	e joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		10 in.	Vitrified Clay Pipe			


			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	2				0	0							
2	0	2				0	0							
3	0	3	23	4431	2.9	0	0	0	0000	0.0	23	2.9	4.4	
4	0	16				0	0							
5	0	0				0	0							






Start date/time	: Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200916 08:	,	tion during	K.Lang	UO-200-70308438	2581-1743	
	survey	9				
Owner:	Customer	:	Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning	<u> </u>	TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON CT	RISLEY F	RD		Sanitary Sewage Pipe		
Upstream MH N	0:	Downstrea	m MH No:	Direction:	Total length:	Length surveyed:
2581		1743		U	174.135 ft.	174.133 ft.
Purpose: Pi	ipe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		12 in.	Vitrified Clay Pipe		V19 (EASEMENT)	


			Structura	al:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	2							
2	0	0				0	0							
3	0	0	1	1100	1.0	0	0	14	4312	2.8	15	2.5	4.3	
4	0	0				0	12							
5	0	0				0	0							






Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200910 12:3		ion during	K.Lang	UO-200-70308438	1328-2138	
	survey	ion during				
Owner:	Customer		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON	SCOTT D	R		Sanitary Sewage Pipe		
Upstream MH No	):	Downstrea	m MH No:	Direction:	• Total length:	Length surveyed:
1328		2138		D	193.050 ft.	193.048 ft.
Purpose: Pip	pe joint length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related —		8 in.	Vitrified Clay Pipe		V19	

			Structura	ıl:				O&M:				Over	all:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	1				0	0							
2	0	4				0	0							
3	0	3	12	4131	2.4	0	0	0	0000	0.0	12	2.4	4.1	
4	0	4				0	0							
5	0	0				0	0							





Start date/time:	Weather:		Surveyed by:	Certificate number:	Pipe segment ref.:	
20200910 13:12	Dry - No	ion during	K.Lang	UO-200-70308438	2140-2139	
	survey	ion during				
Owner:	Customer:		Pre-cleaning:	Date cleaned:	Project name:	
			Light Cleaning		TIG001-23	
City:	: Street:		Location code:	Pipe use:	Drainage area:	Flow control:
VERNON	VINE DR			Sanitary Sewage Pipe		
Upstream MH No:		Downstrea	m MH No:	Direction:	· Total length:	Length surveyed:
2140		2139		U	125.200 ft.	125.196 ft.
Purpose: Pipe jo	nt length:	Height:	Material:	LateralsCounter:	Additional info:	
Maintenan ce Related ———		8 in.	Vitrified Clay Pipe		V19	

			Structura	ıl:				O&M:				Over	rall:	
Grade	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Defects	Segment Grade	Pipe Rating	Quick Rating	Pipe Rating Index	Pipe Rating	Pipe Rating Index	LoF	Risk
1	0	0				0	1							
2	0	2				0	0							
3	0	3	10	5131	3.3	0	0	1	1100	1.0	11	2.8	5.1	
4	0	0				0	0							l
5	0	5				0	0							

