

Middle Tankerhoosen River Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Middle Tankerhoosen River
- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup



Outfalls

- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

0 1,200 2,400 Feet



Lower Tankerhoosen River Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Lower Tankerhoosen River
- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup



Outfalls

- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

0 825 1,650 Feet



Tucker Brook Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Tucker Brook

Stream and Riparian Areas

- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup


Outfalls

- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

0 825 1,650 Feet





Walker Reservoir Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Walker Reservoir
- Stream and Riparian Areas
- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup
- Outfalls**
- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization
- Potential Fish Passage Barriers**
- Severe
- Moderate
- Minor

0 740 1,480 Feet



FUSS & O'NEILL
Disciplines to Deliver

Gages Brook Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Gages Brook

Stream and Riparian Areas

- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup

Outfalls

- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

0 740 1,480 Feet



**Gages Brook South Tributary Subwatershed
Watershed Management Plan - Stream Corridor Recommendations**

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Gages Brook South Tributary
- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup

Outfalls



- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

Scale: 0, 740, 1,480 Feet

North Arrow: N



Clarks Brook Subwatershed
Watershed Management Plan - Stream Corridor Recommendations

Legend

- Tankerhoosen River Watershed
- Municipal Boundary
- Waterbody
- Marsh
- Stream
- Assessed Stream Reach
- Clarks Brook

Stream and Riparian Areas

- Severe Stream Bank Erosion
- Impacted Riparian Buffer
- Recommended Stream Cleanup

Outfalls

- Recommended Illicit Discharge Investigation
- Potential Stormwater Retrofit
- Stream Stabilization
- Discharge Investigation & Potential Retrofit
- Potential Retrofit and Stream Stabilization

Potential Fish Passage Barriers

- Severe
- Moderate
- Minor

0 1,300 2,600 Feet

